

CAL: 300 WIN MAG

TRACKING # TLW 1407
PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-0	
				RDS. FIRED	TOTAL RDS.
JW / BL	2/16/2004	OUT OF BOX	INSPECTION OK		
SW / BL	2/16/2004	HEADSPACE BEFORE	PROOF MIN + .005		
SW / BL	2/16/2004	PROOF ROUND		1	1
SW / BL	2/16/2004	HEADSPACE AFTER	PROOF MIN + .005		
SW/JW/BL	2/16/04	Indents			
SW / BL	2/17/04	SEAR LIFT	SEE DATA SHEET		
SW / BL	2/17/04	ENGAGEMENT	↓ ↓ ↓		
SW / BL	2/17/04	TRIGGER PULL			
JS	2/19/04	200 Rd Jack Funct.		200	201
BL	2/27/04	500 Rd Ext. Endur Test		500	701
BL	3/8/04	Clean/Inspection	see Inspection Sheet		
BL	3/9/04	Clean/Inspection	see Inspection Sheet		

Logform

— 6 —

Confidential - Subject to Protective Order

Williams v. Remington

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-21

TLW #: TLW1303

Date: 3 19 104

Inspector: BL

Round Level: 201

☒ Measure Headspace min .005

☒ Inspect Take Down Screws for loosening. Center screw 1/2 turn - Top screw 1/2 turn 83

☒ Sear Engagement: 1st. .0334 2nd. .0347 3rd. .0342 Ave. .0341 spec. .025" to .030"

☒ Reset Sear Engagement if Required: 1st. .0273 2nd. .0283 3rd. .0288 Ave. .02813

☒ Trigger Pull: 1st. 5.225 2nd. 5.210 3rd. 5.172 Ave. 5.202 spec- 4.5 lb. to 5.5 lb.

☐ Reset Trigger Pull if Required: 1st. 2nd. 3rd. Ave.

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: Cam surface, locking lugs some sign of wear

☒ Inspect stock for any signs of cracking or other failure. cracked Stock at center screw hole

☐ Other items of note:

TLW1216

Remington Confidential

ET21109

CAL: 300 WIN MAG

TRACKING # TLW 1407
PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS	AT START-0
				RDS. FIRED	TOTAL RDS.
JW / BL	2/16/2004	OUT OF BOX	INSPECTION OK		
SW / BL	2/16/2004	HEADSPACE BEFORE	PROOF MIN + .005		
SW / BL	2/16/2004	PROOF ROUND		1	1
SW / BL	2/16/2004	HEADSPACE AFTER	PROOF MIN + .005		
SW / JW / BL	2/16/04	INDENTS			
SW / BL	2/17/04	SEAR LIFT	SEE DATA SHEET		
SW / BL	2/17/04	ENGAGEMENT			
SW / BL	2/17/04	TRIGGER PULL			
JS	2/19/04	200 Rd Jack Funct.		200	201
BL	2/27/04	500 Rd Ext. Endur Test		500	701
BL	3/9/04	Clean / Inspection	See Inspection Sheet		

Logform

60

Confidential - Subject to Protective Order

ET21110

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A22

TLW #: TLW1303

Date: 3 / 9 / 04

Inspector: BL

Round Level: 701

☒ Measure Headspace min +.005

☒ Inspect Take Down Screws for loosening. Topscrew 4 turn - Center screw 8 turn

☒ Sear Engagement: 1st. .0299 2nd. .0291 3rd. .0301 Ave. .0297 spec. .025" to .030"

☐ Reset Sear Engagement if Required: 1st. .0299 2nd. .0291 3rd. .0301 Ave. .0297

☒ Trigger Pull: 1st. 4.728 2nd. 4.839 3rd. 4.608 Ave. 4.725 spec- 4.5 lb. to 5.5 lb.

☐ Reset Trigger Pull if Required: 1st. 4.728 2nd. 4.839 3rd. 4.608 Ave. 4.725

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: cam surface, locking lugs, ~~and~~ Bolt Stop some sign of wear

☒ Inspect stock for any signs of cracking or other failure. cracked stock at center screw hole

☐ Other items of

note:

TLW1216

Remington Confidential

ET21111