

CAL: 300 WIN MAG

TRACKING # TLW 1407
PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-0	
				RDS. FIRED	TOTAL RDS.
JW / BL	2/16/2004	OUT OF BOX	INSPECTION OK		
SW / BL	2/16/2004	HEADSPACE BEFORE	PROOF MIN + .006		
SW / BL	2/16/2004	PROOF ROUND		1	1
SW / BL	2/16/2004	HEADSPACE AFTER	PROOF MIN + .007		
SW/JW/BL	2/16/04	INDENTS			
SW/BL	2/17/04	SEAR LIFT	SEE DATA SHEET		
SW/BL	2/17/04	ENGAGEMENT			
SW/BL	2/17/04	TRIGGER PULL			
JS	2/19/04	200rd Jack Funct.		200	201
BL	2/27/04	500Pd Ext. Endur Test		500	701
PL	3/9/04	Clean/Inspection	See Inspection Sheet		

Logform

ET21116

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A25

TLW #: TLW1303

Date: 8 19 103

Inspector: BL

Round Level: 701

- ☒ Measure Headspace mint .006
- ☒ Inspect Take Down Screws for loosening. Top screw slight movement - counter screw 1/4 turn 83
- ☒ Sear Engagement: 1st. .0330 2nd. .0324 3rd. .0331 Ave. .3283 spec. .025" to .030"
- ☒ Reset Sear Engagement if Required: 1st. .0297 2nd. .0297 3rd. .0297 Ave. .0297
- ☒ Trigger Pull: 1st. 4.077 2nd. 3.839 3rd. 3.934 Ave. 3.950 spec- 4.5 lb. to 5.5 lb.
- ☐ Reset Trigger Pull if Required: 1st. 4.750 2nd. 4.719 3rd. 4.723 Ave. 4.747
- ☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: cam surface, locking lugs sign of some wear
bolt stop - excessive wear
- ☒ Inspect stock for any signs of cracking or other failure: crack & stock at center screw hole
- ☐ Other items of note: _____

TLW1216

Remington Confidential

ET21117