

CAL: 300 WIN MAG

TRACKING # TLW 1407
PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-0	
				RDS. FIRED	TOTAL RDS.
JW / BL	2/16/2004	OUT OF BOX	INSPECTION OK		
SW / BL	2/16/2004	HEADSPACE BEFORE	PROOF MIN + .005		
SW / BL	2/16/2004	PROOF ROUND		1	1
SW / BL	2/16/2004	HEADSPACE AFTER	PROOF MIN + .005		
SW / JW / BL	2/16/04	INDENTS			
SW / BL	2/17/04	SEAR LIFT	SEE DATA SHEET ↓ ↓ ↓		
SW / BL	2/17/04	ENGAGEMENT			
SW / BL	2/17/04	TRIGGER PULL			
JK	2/19/04	200 Rd JACK Funct.		200	201
BL / JW	3/1/04	500 Rd Ext. Endurance Test		500	201
BL	3/9/04	Blen Inspection	See Inspection Sheet		

Logform

ET21118

Confidential - Subject to Protective Order
Williams v. Remington

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-26

TLW #: TLW1303

Date: 3 19 104

Inspector: BL

Round Level: 701

☒ Measure Headspace min+.005

☒ Inspect Take Down Screws for loosening. Top screw 3/4 turn - Center 1/8 turn

☒ Sear Engagement: 1st. .0349 2nd. .0349 3rd. .0349 Ave. .0349 spec. .025" to .030"

☒ Reset Sear Engagement if Required: 1st. .0287 2nd. .0285 3rd. .0284 Ave. .02843

☒ Trigger Pull: 1st. 5.641 2nd. 5.719 3rd. 5.818 Ave. 5.659 spec- 4.5 lb. to 5.5 lb.

☒ Reset Trigger Pull if Required: 1st. 5.374 2nd. 5.244 3rd. 5.208 Ave. 5.275

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: Cam surface, locking lugs, bolt stop some signs of wear

☒ Inspect stock for any signs of cracking or other failure: Cracked stock at center screw hole

☐ Other items of note: _____

TLW1216

Remington Confidential

ET21119