

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A75

TLW #: TLW1303

Date: 01 1 19 1 09

Inspector: JS/BL

Round Level: _____

☒ Measure Headspace min +.007

☒ Sear Engagement: 1st. .0282 2nd. .0265 3rd. .0275

Ave. .0274 spec- .020" to .025"

Resetting

.0245

Reset Trigger

4.616

☒ Trigger Pull: 1st. 4.139 2nd. 3.984 3rd. 3.736
4.631 4.459 4.758

Ave. 3.953 spec- 4 lb. to 5.5 lb.

☒ Check Take-Down Screws and Re-tighten if necessary.

☒ Inspect extractor & bolt face area. Broken extractor

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive

wear: BOLT STOP some wear, locking lugs some wear

☒ Inspect stock for any signs of cracking or other failure.

☒ Other items of

note: magazine Box is protruding - receiver insert has a defect must
be in the mold.

TLW1303

Remington Confidential

ET21299