

CAL: 300 WIN MAG

TRACKING # TLW 1303
PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-0	
				RDS. FIRED	TOTAL RDS.
SW/PA	12/19/03	Out of box Inspection	TLW1303A		
JS	12/22/03	De-torque Scope Cross Bolt screws	Front 30 Rear 30		
BL		Head space	min +.005		
BL		Proof	Tight to open Emblem on bottom of stock fell off	1	1
BL	12/22/03	Head space	min +.005		
JS/BL	12/22/03	Depth Front Take down Screw hole			
BL	12/23/03	Firing Pin Indent	.022-.023-.022 Avg .022		
JS	12-29-03	Sear/Trigger Engagement	Avg. .0259		
JS	12-29-03	Sear lift	.0178		
SW/JS	1/13/04	Change out bolt head			
SW/JS	1/13/04	Head space	Min +.006		
SW/JW	1/13/04	Proof Rd		1	2
SW/JW	1/13/04	Head space 2 fttr proof	Min +.007		
Blee	1/15/03	word JACK Funct test	magazine Box hard to take from magazine well / 11 FTE Bolt hard to close	200	202
SW	1-15-03	Head space Min +.007	(Front Takedown screw loose)		
BL	1-16-04	Shoulder Fire	magazine came out / Bolt stop not functioning properly 1 FTE	20	222
JS/BL	1-20-04	Clean & Inspect	see Inspection sheet		

Logform

ET21338