

Part Name:	trigger															
Drawing Num:	D-300483	NOTE: Dimension identifiers will be provided on the prints supplied by engineering & the CAD group.														
TLW Number:	1383															
Revision Level:		INSTRUCTIONS:														
Vendor:		1. STAMP ALL PARTS WITH AN I.D. NUMBER AND CHANGE I.D. AT TOP OF PAGE CORRESPONDINGLY.														
Requisition #:		2. TAG PARTS ONLY IF STAMPING IS NOT POSSIBLE.														
Material:		3. ENTER FEATURE DESCRIPTIONS WHEN POSSIBLE (OPTIONAL).														
Hardness:		4. WHEN COMPLETE, RETURN ALL PARTS TO ENGINEER IN ORIGINAL SHIPPING CARTON (IF POSSIBLE) AND DRAWING WITH IDENTIFIERS.														
Metallurgist:		INSPECTOR NOTES:														
Engineer:	Mike Kearney															
Inspected by:	Steve Wade															
Date:	1/29/03															
Reviewed by:																
Date:																

identifier	feature description	DIM	plus	minus	A-41	A-42	A-43	A-44	A-45	A-46	AVG	STDEV	Method
A	I.D.	0.1259	0.0005	0.0005	.1260-	.1260-	.1260-	.1255+	.1260-	.1260-	#DIV/0!	#DIV/0!	PIN
B											#DIV/0!	#DIV/0!	
C											#DIV/0!	#DIV/0!	
D											#DIV/0!	#DIV/0!	
E											#DIV/0!	#DIV/0!	
F											#DIV/0!	#DIV/0!	
G											#DIV/0!	#DIV/0!	
H											#DIV/0!	#DIV/0!	
I											#DIV/0!	#DIV/0!	
J											#DIV/0!	#DIV/0!	
K											#DIV/0!	#DIV/0!	
L											#DIV/0!	#DIV/0!	
M											#DIV/0!	#DIV/0!	
N											#DIV/0!	#DIV/0!	
O											#DIV/0!	#DIV/0!	
P											#DIV/0!	#DIV/0!	
Q											#DIV/0!	#DIV/0!	
R											#DIV/0!	#DIV/0!	
S											#DIV/0!	#DIV/0!	
T											#DIV/0!	#DIV/0!	
U											#DIV/0!	#DIV/0!	
V											#DIV/0!	#DIV/0!	
W											#DIV/0!	#DIV/0!	
X											#DIV/0!	#DIV/0!	
Y											#DIV/0!	#DIV/0!	
Z											#DIV/0!	#DIV/0!	