## CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

## Clean & Inspect Checklist

Model: 710 Extruded Receiver "Magnum Caliber"

	Project: 241314	TLW #: TLW1689	
	Date: 2 122 105	·	
	Gun Test #	S/N 7/202765	, 4 
/	Round Level: 72/	Inspector: 8.LEC	83
Measure Headsp	ace mint oos.		
Check Takedown	Screw Torque @ Disassembly: Frt_	45 , Center 2.6. , Rear /0	
Sear Engagement	t: 1 <sup>st</sup> 0248 2 <sup>nd</sup> 245 3 <sup>rd</sup>	275 Ave. 10246 spec025"	to.030"
Reset Sear Engag	gement if Required: 1st. 2nd.	3 <sup>rd</sup> . Ave	<del></del> -
Trigger Pull:	1st. 4.985 290 4. 925 3rd. 5.00	4 Ave. <u>4.92/</u> spec- 4.5 lb. to	6 lb.
Reset Trigger Pu	ll if Required 2 1 1 . 2 nd. 2 nd.	3 <sup>rd</sup> Ave	
78.V	rol Insert for any signs of cracking o	rother	
faffure.	OK	·	
Other items of			
.की.हैं.हैं. कि.हे	<u> </u>		<del></del>
	·		p. Asia.
Torque Takedow	n Screws @ Reassembly: SPEC- Frt	75 in lbs, Center- 30-35 in lbs, Rear- 15 in lb	os.
		4 1 1	
			TLW1216
	Remington (		

ET21907