

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Extruded Receiver "Magnum Caliber"

Project: 241314

TLW #: TLW1689

Date: 3 12 105

Gun Test # A-31

S/N 71202744

Round Level: 2229

Inspector: B. Lee

83

- ☒ Measure Headspace min+.006
- ☒ Check Takedown Screw Torque @ Disassembly: Frt 50, Center 25, Rear 10
- ☒ Sear Engagement: 1st .002 2nd .0303 3rd .0300 Ave. _____ spec- .025" to .030"
- ☐ Reset Sear Engagement if Required: 1st _____ 2nd _____ 3rd _____ Ave. _____
- ☒ Trigger Pull: 1st 4.44 2nd 4.184 3rd 4.053 Ave. 4.294 spec- 4.5 lb. to 6 lb.
- ☒ Reset Trigger Pull if Required: 1st 4.971 2nd 4.430 3rd 4.776 Ave. 4.726
- ☒ Inspect Firecontrol Insert for any signs of cracking or other failure. OK
- ☒ Other items of note: Bolt stop worn & L.H.L.
- ☒ Torque Takedown Screws @ Reassembly: SPEC- Frt- 75 in lbs, Center- 30-35 in lbs, Rear- 15 in lbs.

TLW1216

Remington Confidential

ET22009