

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Extruded Receiver "Std. Caliber"

Project: 241314

TLW #: TLW1689

Date: 3 / 1 / 05

Gun Test # A-11

S/N 71202772

Round Level: 1711

Inspector: B. LEE

83

- ☒ Measure Headspace mint. 0.044
- ☒ Check Takedown Screw Torque @ Disassembly: Frt 45, Center 35, Rear 15
- ☒ Sear Engagement: 1st .0244 2nd .0250 3rd .0252 Ave. .0248 spec- .020" to .025"
- ☐ Reset Sear Engagement if Required: 1st 2nd 3rd Ave.
- ☒ Trigger Pull: 1st 5.921 2nd 5.918 3rd 5.831 Ave. 5.890 spec- 4 lb. to 5.5 lb.
- ☒ Reset Trigger Pull if Required: 1st 4.844 2nd 4.868 3rd 4.991 Ave. 4.901
- ☒ Inspect Firecontrol Insert for any signs of cracking or other failure. OK
- ☐ Other items of note:
- ☒ Torque Takedown Screws @ Reassembly: SPEC- Frt- 50 in lbs, Center- 30-35 in lbs, Rear- 15 in lbs.

TLW1216

Remington Confidential

ET22063