CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Extruded Receiver "Std. Caliber"

Middel; /10 Extruded Receiver Stu. Camber			
	Project: 241314	TLW #: TLW1689	
	Date: 2 / 22 / 05		
	Gun Test #	S/N 7/202776	
/	Round Level:	Inspector: BLEE	5 3
Measure Headspace	ce mintooy.		5(\$).
Check Takedown S	Screw Torque @ Disassembly: Frt /5	Center 20 , Rear 15	
Sear Engagement:	1 ⁵¹ 0247 2 nd 0246 3 rd 0249	spec020" to.025"	,
Reset Sear Engage	ment if Required; 1 st . 2 nd .	3 ^{to} Ave	
Trigger Pull:	15 37243 2nd 5.36C 3rd 3.083	Ave. 5, 2/4 spec- 4 lb. to 5.5 lb.	
Reset Trigger Pull	if Required: 15 2 nd 3	rd. Ave	
Inspect Firecontre	of Insert for any signs of cracking or other		
failure	OK	<u> </u>	_ _
	,	- V.	
Other items of			
note:			
·		·	
	•		
Torque Takedown	Screws @ Reassembly: SPEC Frt- 50 in	lbs, Center- 30-35 in lbs, Rear- 15 in lbs.	
. Torque Tanous VIII		,	
			TLW1216
Remington Confidential			