

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Extruded Receiver "Std. Caliber"

Project: 241314

TLW #: TLW1689

Date: 2 125 105

Gun Test # A2

S/N 71202775

Round Level: 1211

Inspector: B. LEE

83

- Measure Headspace min^t.004
- Check Takedown Screw Torque @ Disassembly: Frt 30, Center 30, Rear 10
- Sear Engagement: 1st. .0263 2nd. .0264 3rd. .0267 Ave. .0249 spec-.020" to .025"
- Reset Sear Engagement if Required: 1st. .0251 2nd. .0250 3rd. .0248 Ave. _____
- Trigger Pull: 1st. 6.179 2nd. 5.682 3rd. 5.702 Ave. 5.854 spec- 4 lb. to 5.5 lb.
- Reset Trigger Pull if Required: 1st. _____ 2nd. _____ 3rd. _____ Ave. _____
- Inspect Firecontrol Insert for any signs of cracking or other failure. OK
- Other items of note: _____
- Torque Takedown Screws @ Reassembly: SPEC- Frt- 50 in lbs, Center- 30-35 in lbs, Rear- 15 in lbs.

TLW1216

Remington Confidential

ET22207