CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Extruded Receiver "Std. Caliber"

		Project: 241314	TLW #: TLW1689	
		Date: 2 / 17 / 05		
	•	Gun Test #	S/N 7/202780	
		Round Level: 70/	Inspector: B. LEE	
a	Measure Headspace	mint.004.		
0	Check Takedown Sc	rew Torque @ Disassembly: Frt35	, Center 25 , Rear /5	
a	Sear Engagement:	1 st . 10236 2 nd 0245 3 rd 0247	Ave spec020" to.025	;"
	Reset Sear Engagem	ent if Required: 1 st . 2 nd .	3 rd . Ave	
2 ′	Trigger Pull: 1 st	1. 49 20: 2 ^{id} . 4.886, 3 rd . 4.75 5	Ave. 4.853 spec- 4 lb. to 5.5 lb.	
	Reset Trigger Pull.if	Required: 1st. 2nd. 3rd.	Ave	
ם	Inspect Firecontrol	Insert for any signs of cracking or other	•	
	failure.	OK		
<u>د</u> ⊡	Other items of			
	7			
- TO/	7 7 7 1 1 6	O.D	Contra 20 25 in the Day 15 in the	
⊿	Torque Takedown S	Screws @ Reassembly: SPEC- Frt- 50 in lbs	s, Center- 30-35 in lbs, Rear- 15 in lbs.	
				TLW1216
		Remington Confid	ential	