

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Extruded Receiver "Std. Caliber"

Project: 241314

TLW #: TLW1689

Date: 2 / 17 / 05

Gun Test # A-5

S/N 71203237

Round Level: 701

Inspector: B. LEE

83

- ☒ Measure Headspace min+.003.
- ☒ Check Takedown Screw Torque @ Disassembly: Frt 40, Center 30, Rear 10
- ☒ Sear Engagement: 1st. .0236 2nd. .0249 3rd. .0245 Ave. .0243 spec-.020" to .025"
- ☐ Reset Sear Engagement if Required: 1st. 2nd. 3rd. Ave.
- ☒ Trigger Pull: 1st. 5.975 2nd. 5.718 3rd. 5.617 Ave. 5.765 spec- 4 lb. to 5.5 lb.
- ☒ Reset Trigger Pull if Required: 1st. 5.316 2nd. 5.016 3rd. 4.972 Ave. 5.111
- ☒ Inspect Firecontrol Insert for any signs of cracking or other failure. OK
- ☐ Other items of note:
- ☒ Torque Takedown Screws @ Reassembly: SPEC- Frt- 50 in lbs, Center- 30-35 in lbs, Rear- 15 in lbs.

TLW1216

Remington Confidential

ET22239