

PROJECT # 241230
ENG: MIKE KEENEY
SHOOTER: BOB LEE

HEAT AND HUMIDITY TEST
GUN # A-4
SERIAL # 71163352

TRACKING # TLW 1530U
DATE 9/8/04

ROOM AND SHOT 20 ROUNDS.

LOADING ONE ROUND IN CHAMBER AND FOUR IN THE MAGAZINE.

CYCLED SAFETY EVERY FIFTH ROUNDS.

PUT GUN A-4 BACK IN ENVIRONMENTAL TEST CHAMBER FOR 2 HOURS.

3 AFTER 2 HOURS TOOK GUN A-4 AND 20 ROUNDS AMMO OUT OF ENVIRONMENTAL TEST CHAMBER TO SHOOTING ROOM AND SHOT 20 ROUNDS.

LOADING ONE ROUND IN CHAMBER AND FOUR IN THE MAGAZINE.

CYCLED SAFETY EVERY FIFTH ROUNDS.

PUT GUN A-4 BACK IN ENVIRONMENTAL TEST CHAMBER FOR 2 HOURS.

4 AFTER 2 HOURS TOOK GUN A-4 AND 20 ROUNDS AMMO OUT OF ENVIRONMENTAL TEST CHAMBER TO SHOOTING ROOM AND SHOT 20 ROUNDS.

LOADING ONE ROUND IN CHAMBER AND FOUR IN THE MAGAZINE.

CYCLED SAFETY EVERY FIFTH ROUNDS.

PUT GUN A-4 BACK IN ENVIRONMENTAL TEST CHAMBER FOR 2 HOURS.

5 AFTER 2 HOURS TOOK GUN A-4 AND 20 ROUNDS AMMO OUT OF ENVIRONMENTAL TEST CHAMBER TO SHOOTING ROOM AND SHOT 20 ROUNDS.

LOADING ONE ROUND IN CHAMBER AND FOUR IN THE MAGAZINE.

CYCLED SAFETY EVERY FIFTH ROUNDS.

PUT GUN A-4 BACK IN ENVIRONMENTAL TEST CHAMBER FOR 2 HOURS.

6 AFTER 2 HOURS TOOK GUN A-4 AND 20 ROUNDS AMMO OUT OF ENVIRONMENTAL TEST CHAMBER TO SHOOTING ROOM AND SHOT 20 ROUNDS.

LOADING ONE ROUND IN CHAMBER AND FOUR IN THE MAGAZINE.

CYCLED SAFETY EVERY FIFTH ROUNDS.

7 CLEANED AND INSPECTED (OK)

MALFUNCTIONS 0

CONFIDENTIAL 83

ET22816