CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 EXTRUDED RECEIVER	Project : 241230
Rifle: <u>4-7</u>	TLW #: TLW1530
Date: 8 / 3 / 04	Inspector: B.Ce
Round Level: 2221	
Measure Headspace	
Sear Engagement: 1 st 0244 2 nd 0245 3 rd 0241	Ave. 102443 spec020" to 025"
Reset Sear Engagement if Required: 1st. 2nd. 3r	d Ave
Trigger Pull: 1st. 4.534 2nd. 4.523 3rd. 4.472	Ave: 4540 spec-4 lb. to 5.5 lb.
Reset Trigger Pull if Required: 1st. 250. 350.	Ave
Inspect cam surface, locking lugs and bolestop for signs of excess	ive
wear: bolt sto is so no wear	
Inspect stock for any signs of cracking or other	·
	•
Other items of	
note:	
	·
	TLW1216

ET22888