

RIFLE # A-10
S.N. 71163353
CAL. 7MM REM MAG

M / 710 EXTRUDED RECEIVER D.A.T.

PROJECT: #
TLW: # 1530

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START- RDS. FIRED	TOTAL RDS.
B.Lee	7-12-04	Initial Headspace	min + .002 TLW1530B		
B.Lee	7-13-04	Proof	OK - Shell stuck to bolt head TLW1530C	1	1
B.Lee	7-13-04	Re-measure headspace	min + .003 TLW1530D		
B.Lee	7-13-04	Indents	.020 .020 .020 Avg. .020 TLW1530E		
SW	7-14-04	Engagement	See data sheet TLW1530F		
SW	7-15-04	Sear / Firing Pin Head Engagement	See data sheet TLW1530G		
SW	7-15-04	Trigger Pull	See data sheet TLW1530H		
BL	7-15-04	Safety ON / OFF Forces	See data sheet TLW1530I		
BL	7-15-04	Bolt opening / closing Forces	See data sheet TLW1530J		
SW	7-16-04	Sear LIFT	See data sheet TLW1530F		
BL	8-10-04	Basic Jack Function Test	X 20 Rds. TLW1530N	20	21
JS	8-10-04	Receiver Modified	Machined chamber to aid in feeding ammo		
BL	8-10-04	200 Rd Basic Jack Function Test	2 stem Lugs TLW1530N	180	201
SW/DM	8/13/04	Shoulder Function Test	0 Malfunctions TLW1530O	20	221
BL/JS	8/13/04	Accuracy		20	241
SW	8/16/04	Clean + Inspect	OK Headspace Min + .003 TLW1530A		
SW	8/19/04	Put stock on gun	with new material ORds		
JS	8/24/04	Endurance	OK TLW1530Q	500	741
SW	8/30/04	Clean + Inspect	OK Headspace Min + .003 TLW1530R		
SW/JW	8/30/04	S22mi Juv-Off	Pass TLW1530Y		
SW/JW	8/30/04	S22mi Rotation	Pass TLW1530Z		
SW/JW	8-31-04	S22mi Drop	Pass (Broken Tang I) TLW1530AA		
SW	9/1/04		Took insert from A-5		
SW/JW	9-2-04	Extended Juv-Off	18" Pass TLW1530AB		
SW/JS	9-2-04	Extended Juv-Off	24" Pass TLW1530AB		
SW/JW	9-2-04	Extended Juv-Off	36" Failed TLW1530AB		
			Broken Tang off insert		

DAILY DATA SHEET

Remington Arms Confidential

Page 1

ET22922

Confidential - Subject to Protective Order

Williams v. Remington