

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 EXTRUDED RECEIVER

Project: 241230

Rifle: A-11

TLW #: TLW1530

Date: 9 / 1 / 04

Inspector: SW

Round Level: 1240

- ☒ Measure Headspace Min 4.002
- ☒ Sear Engagement: 1st. 0343 2nd. 0341 3rd. 0344 Ave. 03426 spec. .010" to .025" 83
- ☐ Reset Sear Engagement if Required: 1st. _____ 2nd. _____ 3rd. _____ Ave. _____
- ☒ Trigger Pull: 1st. 4.418 2nd. 5.744 3rd. 6.507 Ave. 6.223 spec. 4 lb. to 5.5 lb.
- ☐ Reset Trigger Pull if Required: 1st. _____ 2nd. _____ 3rd. _____ Ave. _____
- ☐ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: locking lugs normal wear, bolt stop little wear
- ☒ Inspect stock for any signs of cracking or other failure. "Normal" 45° crack from recoil lug. They are long but don't appear worse than at 500 rounds.
- ☒ Other items of note: _____

TLW1216

Remington Confidential

ET22956