

CONFIDENTIAL

Remington Arms Company Inc.  
Research & Development Technical Center  
315 West Ring Road  
Elizabethtown, KY 42701

## Clean & Inspect Checklist

Model: 710 EXTRUDED RECEIVER

Project: 241230

Rifle: A-11

TLW #: TLW1530

Date: 9 / 2 / 04

Inspector: SW

Round Level: 1740

☒ Measure Headspace Min +.002

☒ Sear Engagement: 1<sup>st</sup>. .0341 2<sup>nd</sup>. .0342 3<sup>rd</sup>. .0340 Ave. .0341 spec. .020" to .025"

☐ Reset Sear Engagement if Required: 1<sup>st</sup>.        2<sup>nd</sup>.        3<sup>rd</sup>.        Ave.       

☒ Trigger Pull: 1<sup>st</sup>. 4.915 2<sup>nd</sup>. 4.953 3<sup>rd</sup>. 5.074 Ave. 4.980 spec. 4 lb. to 5.5 lb.

☐ Reset Trigger Pull if Required: 1<sup>st</sup>.        2<sup>nd</sup>.        3<sup>rd</sup>.        Ave.       

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: locking lugs normal wear, bolt stop little wear

☒ Inspect stock for any signs of cracking or other failure. Stock cracked - no worse Photo taken

☒ Other items of note:         
        
        
      

TLW1216

Remington Confidential

ET22962