ΝN	10 F			# 150390R052
L	al C			
4		MALFUNCTIONS		MALFUNCTIONS
1	1		51	OVOLED OVEETY
2	2		53	CYCLED SAFETY
3 4		CYCLED SAFETY	54	
5	1	FIGLED SAFETT	55	
<u>6</u>	2			CYCLED SAFETY
7	3		57	
8	- 1	CYCLED SAFETY	58	
9	1		59	
0	2			CYCLED SAFETY FIRED 20 RDS AT -20 DEGREE F.
1	3		61	
2	4	CYCLED SAFETY	62	
3	_1		63	OVOLED OF SETTING
4	2			CYCLED SAFETY
5	3	CYCLED SAFETY	65 66	
<u>6</u>	4	OTOLED SAFETT	67	
8	2			CYCLED SAFETY
9	3		69	OTOLLO SALLI
0		CYCLED SAFETY FIRED 20 RDS AT -20 DEGREE F.	70	
1	1	O. OLLO ON ETT. HALL EN HOUSE TO DECIMET.	7.1	
2	2	2.7 a*	72	CYCLED SAFETY
3	3		73	
4		CYCLED SAFETY	74	
5	_1		75	
26	2		4	CYCLED SAFETY
7	3		77	
3	~	CYCLED SAFETY	78	
9	1		79	CYCLED CAFETY FIRED 20 PDC AT 30 DECORE F
) (	2		80	CYCLED SAFETY FIRED 20 RDS AT -20 DEGREE F.
31 32	3	CYCLED SAFETY	81	
52 53:		STOLED SMFE NO. ST. ST. ST. ST. ST. ST. ST. ST. ST. ST	83	
14				CYCLED SAFETY
35	3		85	
36	(10)	CYCLED SAFETY	86	
37.	15 T	<u></u>	87	
38	2		88	CYCLED SAFETY
9			89	
0	4	CYCLED SAFETY FIRED 20 RDS AT -20 DEGREE F.	90	
1	1		91	
12	2			CYCLED SAFETY
43	3		93	
44	4	CYCLED SAFETY	94	
45	1		95	
46	.2		96	CYCLED SAFETY
17	3	OVOLED CASETY	98	
8	4	CYCLED SAFETY	98	
19	1			CYCLED SAFETY FIRED 20 RDS AT -20 DEGREE F.
50	2		100	O TOLLE GALLTT FINLE 20 NOO AT -20 DEGREE F.
—	-		+-	
—			+-	
_	$\vdash$		+-	
			+-	<u> </u>

\* PROJECT # 241230 ENG: MIKE KEENEY SHOOTER: BOB LEE

1.1

## COLD FUNCTION TEST GUN # A-12 SERIAL # 71163359

1.

TRACKING # TLW 1530T DATE 9/8/04

#	1	PLACE GUN A-12 AND 100 ROUND OF AMMO IN FREEZER FOR 15 HOURS AT -20 DEGREE F.
#	2	TOOK GUN A-12 AND 20 ROUNDS OF AMMO OUT OF FREEZER TO SHOOTING ROOM AND SHOT 20 ROUNDS
		LOADING ONE ROUND IN CHAMBER AND THREE ROUNDS IN THE MAGAZINE.
		CYCLED SAFETY EVERY FOURTH ROUNDS.
		PUT GUN A-12 BACK IN FREEZER FOR 2 HOURS.
#	3	AFTER 2 HOURS TOOK GUN A-12 AND 20 ROUNDS OF AMMO OUT OF FREEZER TO TO THE SHOOTING ROOM
		AND SHOT 20 ROUNDS.
		LOADING ONE ROUND IN CHAMBER AND THREE ROUNDS IN THE MAGAZINE.
		CYCLED SAFETY EVERY FOURTH ROUNDS.
		PUT GUN A-12 BACK IN FREEZER FOR 2 HOURS.
#	4	AFTER 2 HOURS TOOK GUN A-12 AND 20 ROUNDS OF AMMO OUT OF FREEZER TO TO THE SHOOTING ROOM
		AND SHOT 20 ROUNDS.
		LOADING ONE ROUND IN CHAMBER AND THREE ROUNDS IN THE MAGAZINE.
		CYCLED SAFETY EVERY FOURTH ROUNDS.
		PUT GUN A-12 BACK IN FREEZER FOR 2 HOURS.
#	5	AFTER 2 HOURS TOOK GUN A-12 AND 20 ROUNDS OF AMMO OUT OF FREEZER TO TO THE SHOOTING ROOM
		AND SHOT 20 ROUNDS.
	-	LOADING ONE ROUND IN CHAMBER AND THREE ROUNDS IN THE MAGAZINE.
		CYCLED SAFETY EVERY FOURTH ROUNDS.
		PUT GUN A-12 BACK IN FREEZER FOR 2 HOURS.
#	6	AFTER 2 HOURS TOOK GUN A-12 AND 20 ROUNDS OF AMMO OUT OF FREEZER TO TO THE SHOOTING ROOM
		AND SHOT 20 ROUNDS.
		LOADING ONE ROUND IN CHAMBER AND THREE ROUNDS IN THE MAGAZINE.
Г		CYCLED SAFETY EVERY FOURTH ROUNDS.
		CLEANED AND INSPECTED ( EVERYTHING: OK )
		MALFUNCTIONS

SHOOTER: BOO LEE SERIAL # 71163359 CAL - 7MM REM MAG

