

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 EXTRUDED RECEIVER

Project: 241230

Rifle: A-15

TLW #: TLW1530

Date: 8 / 30 / 04

Inspector: SW

Round Level: 721

☒ Measure Headspace Min +.006

☒ Sear Engagement: 1st .0338 2nd .0343 3rd .0341 Ave. .03406 spec. .020" to .025" 83

☐ Reset Sear Engagement if Required: 1st 2nd 3rd Ave.

☒ Trigger Pull: 1st 5.830 2nd 6.095 3rd 6.106 Ave. 6.040 spec. 4 lb. to 5.5 lb.

☐ Reset Trigger Pull if Required: 1st 2nd 3rd Ave.

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: locking lugs normal wear, bolt stop little wear.

☒ Inspect stock for any signs of cracking or other failure: Normal 45° crack at recoil lugs - seems smaller than old material.

☒ Other items of note: OK Fire control bracket screw loose (retighten)

TLW1216

Remington Confidential

ET23032