

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 EXTRUDED RECEIVER

Project: 241230

Rifle: A-15

TLW #: TLW1530

Date: 9 / 1 / 04

Inspector: SW

Round Level: 1221

☒ Measure Headspace Min +0.06

☒ Sear Engagement: 1st. .0333 2nd. .0331 3rd. .0332

Ave. .03310 spec. .020" to .025"

83

☐ Reset Sear Engagement if Required: 1st. _____ 2nd. _____ 3rd. _____

Ave. _____

☒ Trigger Pull: 1st. 4.281 2nd. 4.295 3rd. 4.265

Ave. 4.280 spec. 4 lb. to 5.5 lb.

☐ Reset Trigger Pull if Required: 1st. _____ 2nd. _____ 3rd. _____

Ave. _____

☐ Inspect cam surface, locking lugs and bolt stop for signs of excessive

wear: locking lugs no wear, bolt stop little wear

☒ Inspect stock for any signs of cracking or other

failure. "Normal" 45° Crack through 90% of wall. (Like most others in the test)

☒ Other items of

note: OK

TLW1216

Remington Confidential

ET23038