

Franz, Scott

From: Franz, Scott
Sent: Monday, November 06, 2000 9:25 AM
To: Bristol, Il Ronald H.; Golemboski, Matt R.; Diaz, Danny; Keeney, Mike
Cc: Snedeker, Jim; Danner, Dale
Subject: M/710 T & P Conference Call
Importance: High

Issues to discuss at the 10:00 a.m. meeting:

- Visual Inspection Issues as identified by John Trull
 1. ISS Keys missing - (3 of 30)
 2. Stock Sink - Left side
 - 1 of 30 unacceptable (measured .050" sink)
 - Worst case sample identified (measured .042" sink)
 3. Hard Bolt Cycle (translation) - 1 of 30 unacceptable
 - Improved w/cycling
 4. Bolt Stop Detent - 1 of 30 loose
- Measurement/Function Issues
 1. ~~Headspace - 1 of 30 won't close on E-town Min. plug.~~
 2. Fire Control Operation
 - 2 of 30 guns had follow down malfunctions (A-14 & A-26)
 - 1 of 30 inadvertently discharged (A-26)
 3. Bolt Stop Breakage - 1 of 30 during Preliminary measurements