

100 Rd. Jack Function Test Guns B-1 to B-10
 TLW0300Z less B-8 that is out of test for a marketing evaluation of the trigger location
 11/19/00

This is a 100 rd. Basic Jack Function Test performed in the Function & Casualty Range using the std. Remington test jacks.
 Only Remington ammo was used, 20 rds. ea. of 5 types.

GUN #	Serial #	Ammo Types	Lot #	Malfunctions
B-1	71001124	Rem. L30062, 150 GR. MC	L15WB0613	0
		Rem. PRT3006B, 165 gr. NBT	M01NC0525	0
		Rem. R30064, 180 gr.SP	C035SC1326	0
		Rem. R30065, 180 gr. PSP	L05DA25	0
		Rem. R30067, 220 gr. SP	M06NB26	0
Technician-	Jeff Wade			
Comments Noted-	Oiled Bolt @ Start of Test			

GUN #	Serial #	Ammo Types	Lot #	Malfunctions
B-2	71001184	Rem. L30062, 150 GR. MC	L15WB0613	0
		Rem. PRT3006B, 165 gr. NBT	M01NC0525	0
		Rem. R30064, 180 gr.SP	C035SC1326	0
		Rem. R30065, 180 gr. PSP	L05DA25	0
		Rem. R30067, 220 gr. SP	M06NB26	0
Technician-	Jeff Wade			
Comments Noted-	Oiled Bolt @ 21 rds. Magazine difficult to remove.			

GUN #	Serial #	Ammo Types	Lot #	Malfunctions
B-3	71001244	Rem. L30062, 150 GR. MC	L15WB0613	0
		Rem. PRT3006B, 165 gr. NBT	M01NC0525	0
		Rem. R30064, 180 gr.SP	C035SC1326	0
		Rem. R30065, 180 gr. PSP	L05DA25	0
		Rem. R30067, 220 gr. SP	M06NB26	0
Technician-	Jeff Wade			
Comments Noted-	Oiled Bolt @ 21 rds. Grip Cap Fell off gun @ 67 rds. Bolt Difficult to Open			

GUN #	Serial #	Ammo Types	Lot #	Malfunctions
B-4	71001288	Rem. L30062, 150 GR. MC	L15WB0613	0
		Rem. PRT3006B, 165 gr. NBT	M01NC0525	0
		Rem. R30064, 180 gr.SP	C035SC1326	0
		Rem. R30065, 180 gr. PSP	L05DA25	0
		Rem. R30067, 220 gr. SP	M06NB26	0
Technician-	Jeff Wade			
Comments Noted-	Oiled Bolt @ 21 rds.			

GUN #	Serial #	Ammo Types	Lot #	Malfunctions
B-5	71001421	Rem. L30062, 150 GR. MC	L15WB0613	0
		Rem. PRT3006B, 165 gr. NBT	M01NC0525	0
		Rem. R30064, 180 gr.SP	C035SC1326	0
		Rem. R30065, 180 gr. PSP	L05DA25	0
		Rem. R30067, 220 gr. SP	M06NB26	0
Technician-	Jeff Wade			
Comments Noted-	Oiled Bolt @ Start of Test			

ET27996

GUN #	Serial #	Ammo Types	Lot #	Malfunctions
B-6	71001462	Rem. L30062, 150 GR. MC	L15WB0613	0
		Rem. PRT3006B, 165 gr. NBT	M01NC0525	0
		Rem. R30064, 180 gr.SP	C035SC1326	0
		Rem. R30065, 180 gr. PSP	L05DA25	0
		Rem. R30067, 220 gr. SP	M06NB26	0
Technician-	Bob Lee			
Comments Noted-	none			

GUN #	Serial #	Ammo Types	Lot #	Malfunctions
B-7	71001504	Rem. L30062, 150 GR. MC	L15WB0613	2 stem low
		Rem. PRT3006B, 165 gr. NBT	M01NC0525	0
		Rem. R30064, 180 gr.SP	C035SC1326	5 stem low
		Rem. R30065, 180 gr. PSP	L05DA25	2 stem low, 1 misfire rd. 72 (sufficient indent)
		Rem. R30067, 220 gr. SP	M06NB26	2 stem low
Technician-	Bob Lee			
Comments Noted-	11 stem lows & 1 misfire			

GUN #	Serial #	Ammo Types	Lot #	Malfunctions
B-9	71001524	Rem. L30062, 150 GR. MC	L15WB0613	1 stem low
		Rem. PRT3006B, 165 gr. NBT	M01NC0525	0
		Rem. R30064, 180 gr.SP	C035SC1326	7 stem low
		Rem. R30065, 180 gr. PSP	L05DA25	4 stem low
		Rem. R30067, 220 gr. SP	M06NB26	6 stem low
Technician-	Bob Lee			
Comments Noted-	18 stem lows			

GUN #	Serial #	Ammo Types	Lot #	Malfunctions
B-10	71001529	Rem. L30062, 150 GR. MC	L15WB0613	1 stem low
		Rem. PRT3006B, 165 gr. NBT	M01NC0525	0
		Rem. R30064, 180 gr.SP	C035SC1326	0
		Rem. R30065, 180 gr. PSP	L05DA25	0
		Rem. R30067, 220 gr. SP	M06NB26	0
Technician-	Bob Lee			
Comments Noted-	1 stem low			

ET27997