

9132	1	Issue from Crib	26345	32895	92458
8772	140	Demagnetize Springs	92458	26345	32895
8772	145	Tap Hole in Trigger Housing	92458	26345	32895
8772	151	Assemble Trigger Assembly - Stage One - Inspect Connector 100% - Inspect Trigger 100% and Check Connector to Trigger Fit 100%	92458	26345	32895
8772	154	Assemble Trigger Assembly - Stage Two	92458	26345	32895
8772	155	Adjust Trigger Assembly on Comparator 100%	92458	26345	32895
8772	160	Assemble Trigger Assembly - Stage Three	92458	26345	32895
8772	165	Function Check Complete Trigger Assembly 100%	92458	26345	32895
8772	170	Mark Correctly Assembled, Adjusted and Checked Trigger Assembly with Assembly Identification To MRE Crib #29	92458	26345	32895
8772	175R	Repair Rejected Trigger Assemblies	92458	26345	32895

151

Assemble Trigger Assembly - Stage One -
Inspect Connector 100% - Inspect Trigger 100%
and Check Connector to Trigger Fit 100%

Tool Number	Tooling Description
D-44608	File Fixture
C-44604	Flatness Block

ET28268