

83

COMMENTS FROM TECHNICIANS:  
STOCKS TAKE DOWN SCREWS ARE NOT CLUTTERED TO TORQUE SPEC. SOME ARE BARRELY TIGHTENED AT ALL  
SCOPE RING TO MOUNT SCREWS ARE NOT TIGHT