

Phillip Reesor

From: Reesor, Phillip K.
Sent: 07/26/2004 10:13:38 AM
To: Thweatt, Ed T.
CC:
BCC:
Subject: FW: 710-270 Chamber Images

-----Original Message-----

From: Reesor, Phillip K.
Sent: Monday, July 26, 2004 10:11 AM
To: Diaz, Danny; Franz, Scott
Cc: Lance, Kevin D.; Keeney, Mike; Thweatt, Ed T.
Subject: 710-270 Chamber Images

Gentlemen, the above borescope images are of one of the 710 extruded receiver rifle chambers. Basically, we were performing the Jack Function Test on the 270 rifles and this one was very hard to open after firing each shot. Upon inspection with a borescope the above very nasty gooves were found in the chamber. This gun has been pulled from any additional livefire testing and will only be used as a Drop Test sample.

Phillip Reesor