

CONFIDENTIAL

Remington Arms Company Inc.
RESEARCH & DEVELOPMENT TECHNICAL CENTER
315 WEST RING ROAD
ELIZABETHTOWN, KY 42701

TLW 1005

- Malfunctions per ammo type, breakage, and replacement parts used.
- Any failure that requires the gun to be removed from testing completely.
- Notify management of any unusual events or malfunctions immediately.
- Record ammunition lot code information as it is used throughout the test.

TLW1005Q -Clean Shotguns and Inspect:

After each 500 rounds of endurance, unless other wise specified, each shotgun will be disassembled, cleaned and thoroughly inspected.

A list of inspection points will be provided in the gun packet for check-off and sign-off by the inspector. The inspector will be looking for any signs of unusual wear, especially on critical components and surfaces as well as for anything such as cracks or deformed material that might present a safety concern. Photographs will be taken to document unusual wear, damage or other notable characteristics. Use a facsimile of the following Clean & Inspect Checklist.

Special Note: When re-assembling after cleaning and/or inspection the magazine tube extension must be installed with hand-tight force only.

J.R. Snedeker

Page 18 of 29

12/17/02

Remington Confidential

Revision #1.0

C:\Program Files\TCDI\CrackerLoaderREM\REME\email\rawblob\20060120133028A\00024914.doc

Subject to Protective Order - Williams v. Remington