

> Cc: James, Will; Boyles, Derek; Thompson, Jeff; Riley, Gary D.  
> Subject: RE: 8/6/03 Mayfield meeting  
>  
> Here are the items for review.  
>  
> Print Discussions  
> Safety Arm Blank - The arm angle is greater than print requirements, width is to  
narrow on the arm, and the thumb pad is angled downward.  
> Trigger Pull Spring - Free length and wire diameter  
> Sear Return Spring - Wire diameter.  
> Trigger Guard Screw - Outside head profile: radius is too small.  
> Bolt Cam Lock - .060 radius was to be changed to +/- .010 at .070  
> Take Down Screw - Outside head profile: radius is too small. O.D. of head too  
small.  
>  
> Assembly Issues  
> The receiver and bolt cam lock assembly, mag box changes, and the stock fit.  
>  
> A review of our assembly process is needed.  
>  
> Trigger Assembly  
> Brian Rages is needed to set up trigger scan and a review of our process is  
needed.  
>  
> Thanks,  
>  
> Ed Thweatt

> -----Original Message-----  
> From: Stone, Jeff  
> Sent: Tuesday, August 05, 2003 7:45 AM  
> To: Thweatt, Ed T.  
> Cc: Norton, Vince; James, Will  
> Subject: 8/6/03 Mayfield meeting  
> Importance: High  
>  
> Ed, so that Vince I can prepare for the meeting tomorrow, please  
provide us a list of items that we need to address.  
> Thanks,  
> Jeff S