Scott Franz

From: Stone, Jeff Sent: 08/05/2003 10:18:55 AM To: Rages, Brian L CC: Franz, Scott BCC: Subject: FW: 8/6/03 Mayfield meeting Scott, your call. JS > ----Original Message-->From: Thweatt, Ed T. >Sent: Tuesday, August 05, 2003 9:59 AM >To: Stone, Jeff RE: 8/6/03 Mayfield meeting >Subject: >Yes, if at all possible. We believe this will be a big help >Ed > ----Original Message----->From: Stone, Jeff >Sent: Tuesday, August 05, 2003 8:22 AM Thweatt, Ed T. >To: >Cc: James, Will; Rages, Brian L RE: 8/6/03 Mayfield meeting >Subject: >Is Brian Rages needed to make this trip also? > ----Original Message----From: Thweatt, Ed T. Tuesday, August 05, 2003 9:18 AM Sent: Stone, Jeff; Norton, Vince James, Will; Boyles, Derek; Thompson, Jeff; Riley, Gary D. To: Cc: RE: 8/6/03 Mayfield meeting Subject: Here are the items for review. Print Discussions Safety Arm Blank. The arm angle is greater than print requirements, width is to narrow on the arm, and the thumb pad is angled downward. Trigger Pull Spring - Free length and wire diameter. Sear Return Spring - Wire diameter. Trigger Guard Screw Cutside head profile: radius is too small. Bolt Cam Lock - 060 raduis was to be changed to +/-.010 at .070 ... Take Down Screw Outside head profile: radius is too small. O.D. of head too small. The receiver and boil cam lock assembly, mag box changes, and the stock fit. A review of our assembly process is needed. Trigger Assembly Brian Rages is needed to set up trigger scan and a review of our process is needed.

