

## Remington Arms Company Inc. RESEARCH & DEVELOPMENT TECHNICAL CENTER. 315 WEST RING ROAD

A10	X	X	X			500
				400000000000000000000000000000000000000	***************************************	
A11	X	X				120
A12	X	X		20002204		120
A13	X	X			w	120
A14	X	X		3.50		120
A15	X	X				120
	1500	300	3800	1000	3000	9600

## TLW0683S - Clean Rifles and Inspect:

After each 1000 rounds of endurance, unless other wise specified, each rifle will be disassembled, cleaned and thoroughly inspected.

A list of inspection points will be provided in the gun packet for check-off and sign-off by the inspector. The inspector will be looking for any signs of unusual wear, especially on critical components and surfaces as well as for anything such as cracks or deformed material that might present a safety concern. Photographs will be taken to document unusual wear, damage or other notable characteristics.

J.R. Snedeker TLW 0683

Page 28 of 41 Remington Confidential 05/24/06

Revision #1.1