


CONFIDENTIAL



TLW0010

Remington Arms Company Inc.
RESEARCH & DEVELOPMENT TECHNICAL CENTER
315 WEST RING ROAD
ELIZABETHTOWN, KY 42701



Magazine Box showing deformation at front of box. Note also the separated sides of the box where the welds failed.

Magazine Box, opened at front to show weld spot areas where weld failures occurred. This picture is a production box that was tested in the R&D Metallurgical Lab.



Front of Magazine Box showing the small dents due to the impact of the bullet nose on the front of the box.

Jan.2001 Design Acceptance Test Remington M/710 Centerfire Rifle;
R & D Technical Center Project No. 241039; TLW 0010
file: F:\Test Reports \ Firearms Tests \ M710_DAT_REPORT_JAN01_Rev1.doc

Page 28

CONFIDENTIAL

REV. 1 - 09/24/00 - R/SJ/LRM

Subject to Protective Order - Williams v. Remington

BARBER - 5.30.06R0001584

ETE00001583