

		TOTAL	200	2	3	
GUN	SERIAL#	AMMO	RDS.	M.F.	BOLT OVERRIDE	STEM LOW FOLLOW DOWN
A-14	XC 1129	REM R30065 180GR	40			
		REM R30067 220GR	40			
		REM L30062 150GR	40			RD# 81 TRIGGER PIVOT PIN CAME OUT, REPLACED
		REM PRT3006B 165GR	40			
		REM R30063 150GR	40			RD# 178 AND 190 MAG BOX CAME APART
		TOTAL	200			
GUN	SERIAL#	AMMO	RDS.	M.F.	BOLT OVERRIDE	STEM LOW FOLLOW DOWN
A-15	XC 1130	REM R30065 180GR	40			
		REM R30067 220GR	40			
		REM L30062 150GR	40			
		REM PRT3006B 165GR	40			
		REM R30063 150GR	40			
		TOTAL	200			NO PROBLEMS NOTED
MALFUNCTIONS ALL GUNS ALL AMMO TYPES						
		AMMO	RDS.	M.F.	BOLT OVERRIDE	STEM LOW FOLLOW DOWN
		REM R30065 180GR	600		2	3
		REM R30067 220GR	600			
		REM L30062 150GR	600			
		REM PRT3006B 165GR	600			
		REM R30063 150GR	600			
		TOTAL	3000	2	3	

Subject to Protective Order - Williams v. Remington

BARBER - 5.30.06R0003534

ETE00003533