

CONFIDENTIAL

Remington Arms Company Inc.
RESEARCH & DEVELOPMENT TECHNICAL CENTER
315 WEST RING ROAD
ELIZABETHTOWN, KY 42701

RIFLE NUMBER	SERIAL NUMBER	AMMUNITION TYPE	LOT NUMBER	ROUNDS FIRED	MALFUNCTIONS
C-9	71001429	Rem.R30064, 180 gr. SP	K29G C4214	100	Mag. box bottom came off @ 93 & 100 Rounds.
		Rem. L30062, 150 gr. MC	M03G B1	400	0
		Win. SHV30064, 180 gr.	35PC52	100	0
		Rem. L30062, 150 gr. MC	M02G C1	100	0
Technician:	J. Arnold				
Comments:	Magazine box became very difficult to remove from gun, straightened magazine box 220 rounds into test & continue.				
RIFLE NUMBER	SERIAL NUMBER	AMMUNITION TYPE	LOT NUMBER	ROUNDS FIRED	MALFUNCTIONS
C-10	71001683	Rem.R30064, 180 gr. SP	K29G C4214	100	Mag. box bottom came off @ 49,53,65,70,84, & 96 Rounds
		Rem. L30062, 150 gr. MC	M03G B1	100	2 Stem Low
		Fed. P3006G, 150 gr.	A146782320	100	0
		Rem. R30067, 220 gr. SP	M24HB14	100	Mag. box bottom came off @ 22 & 32 rounds.
Technician:	J. Arnold				

Jan. '01 Trial & Pilot Test Remington M710 Centerfire Rifle;
R & D Technical Center Project No. 241039; TLW 0300
File: E:\Test Reports\Firearms Tests\710 T&P_3006\M710_T&P_REPORT_JAN01_Rev0.doc

Page 31

CONFIDENTIAL

REV 0 05/01/06 10:11 AM

Subject to Protective Order - Williams v. Remington

BARBER 5.30.06R000000002

ETE00001941