

Safety Modification Program Offer Summary 2006

The safety modification program has been extended until 12/31/2006 and will continue to cover the following models made prior to 1982:

- Model 700
- Models 600 and 660 (including Mohawk 600)
- Model 721
- Model 722
- XP 100
- 40 X

Program basics:

Cleaning, Inspecting, and removal of bolt-lock feature from safety arm.

Allow customers to have certain older bolt-action firearms modified and updated to allow for unloading and loading of the firearms while the manual safety is kept in the "S" or "On Safe" position. The customer no longer has to move the manual safety to the "F" or "off or Fire" position to load or unload the firearm.

Program is voluntary, that is, customer has the decision whether to participate

Program Cost to Customers and Program Offer:

1. Customer pays \$20.00 for clean, inspect and bolt-lock mechanism removal by Remington Authorized Repair Center or the Remington factory.
2. Customer is provided a safety redemption certificate to complete and submit in order to receive a free blaze orange hat (one hat per certificate). Copies will also be available on the Remington website, www.remington.com or at our toll free number 800-243-9700.
3. For redemption, customer must mail in a copy of their repair receipt and completed certificate to: Remington Safety Center, P.O. Box 700, Madison, NC.
4. Consumer Service Department will verify paperwork is complete, accurate and valid. A request will then be made to send out the hat.
5. Customer information, including serial number will be entered into a redemption data base for future reference.

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025
Phone 800-243-9700 • www.remington.com