

## Steve Perniciaro

---

**From:** Orf, Robert J.  
**Sent:** 01/05/2006 05:56:55 PM  
**To:** Perniciaro, Stephen; Kilborne, Carl C.; Kelly, John W.; Call, Virginia L.; Bullis, Gene R.; Truax, Sheldon F.; Mroz, John B.; Bullis, Gene R.; Call, Virginia L.  
**CC:** Bennett, Gary; Paestella, Michael M.; Diliberto, Joseph  
**BCC:**  
**Subject:** RE: Action Log - 700 FC issues

I do not agree with having the final assemblers adjusting fire controls for trigger pull. We need to get the other items addressed and should be gathering all of the fire controls that are rejected by the builders and have them re-inspected by the fire control assembly department. If these fire controls are set to the specs and do not meet our criteria for creep etc. they should be turned over to engineering for inspection.

DO NOT HAVE FINAL ASSEMBLERS ADJUSTING FIRE CONTROLS!!!!

Thanks

Bob Orf

---

**From:** Perniciaro, Stephen  
**Sent:** Thu 1/5/2006 4:28 PM  
**To:** Orf, Robert J.; Kilborne, Carl C.  
**Cc:** Bennett, Gary  
**Subject:** FW: Action Log - 700 FC issues

FYI

---

**From:** Allen, Gerald R.  
**Sent:** Thursday, January 05, 2006 3:24 PM  
**To:** Pugliese, Joseph M.; Kelly, John W.; Perniciaro, Stephen; VanSickle, William C.; Bullis, Gene R.; Call, Virginia L.; Paestella, Michael M.; Bennett, Gary; Truax, Sheldon F.; Mroz, John B.; Grossman, Daniel A.; Diliberto, Joseph  
**Subject:** Action Log - 700 FC issues