

Bob Orf

From: Becker, Craig
Sent: 10/11/2005 10:02:30 AM
To: Orf, Robert J.
CC:
BCC:
Subject: Activity for W/E 10/7

Bob,

For the previous week, 10-3 thru 10-7, I worked on the following:

-SPL issues, In addition to monitoring the progress of the Engis Bore Hone operator,

I worked with Jim Doolittle on the trigger housing assembly problems. Jim has also given me a to-do list on other SPL issues. This occupied most of my week.

-12 gage FETA issues. I wanted to double check my test results for Friday's meeting.

-M700 fire control issues. I am working with Grippe Supply to test 6-40 taps.

The taps currently in Stores pass inspection, but don't give consistent results in usage. (Oversized Holes)

I've had to special order taps to maintain production. I am working with Grippe and Purchasing to rectify this.

-M750 barrel lug and bolt. I worked with Mike LeMay and Terry Kalka on the first

Run parts that came in during the week. The barrel lug was off on the milled barrel seat radii. (0.010" oversized)

I walked Mike thru all the gages in the new gen bolt line. The sample he had didn't pass for the firing pin hole and the milled cam slots.

Craig S. Becker

Manufacturing Engineer

Remington Arms Co. Inc

14 Hoefler Ave

Ilion, NY 13357

(315) 895-3207

(315) 895-3670 (Fax)

E-mail: craig.becker@remington.com

CONFIDENTIAL