

**Jerry Allen**

---

**From:** Call, Virginia L.  
**Sent:** 09/29/2005 06:56:02 PM  
**To:** Bullis, Gene R.; VanSickle, William C.; Diliberto, Joseph; Allen, Gerald R.  
**CC:**  
**BCC:**  
**Subject:** RE: Demerit reporting

I'm in total agreement with Gene if the standard change everyone should be in agreement, then communicated to the builders & inspectors not just change it during a audit.

Virginia L. Call

-----Original Message-----

**From:** Bullis, Gene R.  
**Sent:** Thursday, September 29, 2005 2:40 PM  
**To:** VanSickle, William C.; Diliberto, Joseph; Allen, Gerald R.; Call, Virginia L.  
**Subject:** RE: Demerit reporting

Lets not over react here! The standard (established long before Joe Diliberto arrived), has been to accept any fire control in a bolt action, as long as it could not be seen by looking down on it from the bottom of the guard, straight on. If we are going to change this standard, discussion should take place between engineering, marketing, quality, and production. Otherwise, we need to go back to basics! Gene.

-----Original Message-----

**From:** VanSickle, William C.  
**Sent:** Thursday, September 29, 2005 2:20 PM  
**To:** Diliberto, Joseph; Bullis, Gene R.; Allen, Gerald R.; Call, Virginia L.  
**Subject:** RE: Demerit reporting  
JOE, FROM NOW ON WE WILL REJECT ALL M/700 GUNS THAT THE TRIGGER ISNT IN THE CENTER OF THE GUARD

-----Original Message-----

**From:** Diliberto, Joseph  
**Sent:** Thursday, September 29, 2005 2:11 PM  
**To:** Allen, Gerald R.  
**Cc:** VanSickle, William C.; Call, Virginia L.; Golem, Todd E.  
**Subject:** RE: Demerit reporting

Jerry,

The way that I saw it, the trigger was outside the guard and should have been rejected. A trigger should be centered and not on the edge of being outside guard.

As far as the 1-2 & 5 demerit calls, the builder was correct in passing the gun. We will look at revising the calculation so that it is not figured as a negative for the inspector.

JOSEPH M. DILIBERTO JR.  
REMINGTON ARMS CO., INC.  
14 HOEFLER AVE  
ILION, NY 13357  
PHONE 315-895-3363 FAX 315-895-3670  
E-MAIL joe.diliberto@remington.com

From: Allen, Gerald R.  
Sent: Thursday, September 29, 2005 8:31 AM  
To: Diliberto, Joseph  
Cc: VanSickle, William C.; Call, Virginia L.  
Subject: Demerit reporting

Joe,

Two things. First it is still being debated that the trigger on the one gun is just inside the guard and that this should not be a 10 demerit. I know this was discussed last Friday and I thought we were going to take it off.

The second is reporting of anything less than 10 demerits. A 1, 2, or 5 demerit is a good gun and should have been placed in the box. This report hinders the packers from doing this as their demerit count climbs because of these. Should the formula be modified, so you can still show a lower demerit, but not include it in a guys count.

Thanks

Jerry