

F. 110 GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL

GENERAL CONDITION: NEW R # : 002626

OUTSIDE WORK: N/O DATE: 2-1-72

FROM: Dunn's Shooter

FIRE AMMO TYPE: _____ ADDITION: N/A

& CONDITION: _____ GUN # : 6310545

PROOF: P.P.F. - M INSP.: 71 TEST: 49 CODE: LT = 2/70

HEADING: O.K. GA./CAL.: 300% S

BREECH OPENING: - CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K. APPROVED: _____

CHAMBER: O.K. APPROVED: _____

TEST: N/O APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

TRIGGER PULL 4 LBS., ENGAGEMENT 0.12 (MIN. 0.020)

MARKS TO BE MADE ON SIDE OF TRIGGER PULL
ON TOP SIDE EDGES (RUE MARKS LOWER RIGHT SIDE)

COMPLAINT: RIFLE DISCHARGED BY ITSELF TWO OF SIX TIMES
FIRE.

INCIDENT: FOLLOW DOWN.

COMMENTS: MARKS ON THE TRIGGER INDICATE FRICTION, THE
COMBINATION OF FRICTION, HEAVY LUBRICATION AND UNDER
MIN. ENGAGEMENT PROBABLY PREVENTED TRIGGER
CONNECTOR RETRACTION CAUSING FOLLOW DOWN.

PLAINTIFF'S
EXHIBIT

3256

AL 0029788

1 of 1