

F No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDLGENERAL CONDITION: NEW R #: 002678OUTSIDE WORK: No DATE: 2-2-72FIRED AMMO TYPE: _____ FROM: BILL DOTSON'S INC.& CONDITION: _____ DECATUR, ILL.PROOF: R.E.P.-A INSP.: 9 TEST: 13 GUN #: 6294075HEADING: O.K. CODE: X5-12/69BREACH OPENING: - GA./CAL.: 270 WIN.RECOIL SHOULDERS: O.K. CHECKED BY: C. PROSSERCHAMBER: O.K. APPROVED: _____TEST: No APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

TRIGGER PULL 6 LBS., ENGAGEMENT 0.20. TRIGGER
BIND IS NOTICEABLE. IN DIS-ASSEMBLING THE TRIGGER
HAS WHAT APPEARS TO BE DRIED STEEL GUARD ON
THE SIDES CAUSING IT TO BIND.

COMPLAINT: "WHEN BOLT IS PUT IN ALL THE WAY THE GUN WILL
GO OFF"

INCIDENT: FOLLOW DOWN

COMMENTS: THE SLUGGISH TRIGGER PROBABLY FAILED TO
RETRACT RESULTING IN A FOLLOW DOWN MALFUNCTION.

PLAINTIFF'S
EXHIBIT

3257

1 of 1
AL 0029789