

F NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 P.M.
 GENERAL CONDITION: GOOD R# : 002116
 OUTSIDE WORK: SCREW MOUNTED - REAR SIGHT DATE: 2-1-72

REAR SIGHT FROM: BLISS FIVE ASSOCIATES, INC.
 FIRED AMMO TYPE: ATTACHED K&H
 & CONDITION: _____ GUN # : 6302807
 PROOF: P.T.R.-5 INSP.: 52 TEST: 12 CODE: WT-1/10
 HEADING: _____ GR./CAL.: 270 M.M.
 BRESCCH OPENING: O.K. CHECKED BY: C. P. ROSS
 RECOIL SHOULDER: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO BROKEN ETC. COMPONENTS. SING E. IN CHAMBER
& CONNECTOR. THREE FIRE. FIVE E. COMPONENT. 002116
IS 020) NONE OF SCREW SEWED - REAR SIGHT
SCREW STAYED BUT NOT HOLDING. SCREW STAYED
ON CONNECTOR NOT HORIZONTAL
 COMPLAINT: RIFLE FIRED FROM DOWN

INCIDENT: FOLLOW DOWN

COMMENTS: THE COMBINATION OF INSUFFICIENT ENGAGEMENT OF
BURRS PROPERLY PREVENTED THE C. RETRACTING
FROM RETRACTING INTO FIRING POSITION CAUSING THE
FIRING PIN TO FOLLOW DOWN.

PLAINTIFF'S
EXHIBIT

3258

1 of 1