

GUN EXAMINATION REPORT NUMBER: MODEL: 700 BDLGENERAL CONDITION: NEW (SOME RUST) R #: 001869OUTSIDE WORK: NO DATE: 1-28-72FIRED AMMO TYPE: FROM: MACY RD, SHTG. CLUB& CONDITION: ECE, PAPROOP: R.E.P.-F INST.: 9 TEST: 55 GUN #: 6290291HEADING: O.K. CODE: RS=11/69BREECH OPENING: - GR./CAL.: 3006 SEC.RECOIL SHOULDERS: O.K. CHECKED BY: C. PROSSERCHAMBER: O.K. APPROVED: TEST: NO APPROVED: COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED:

NO BROKEN COMPONENTS. EXTRACTOR PISTON, BOLT
BODY ALSO. SUBSTANCE RESEMBLING DIED SCUM
ON TRIGGER & SEAR. TRIGGER PULL 2 1/2 LBS. ENGAGE-
MENT .010. LUMP ON BOLT

COMPLAINT: "FIRST SHELL HE TRIED TO CHARGE DISCHARGED"INCIDENT: FOLLOW DOWN

**PLAINTIFF'S
EXHIBIT**

3260

COMMENTS: THE MATERIAL ON THE SEAR & TRIGGER CAUSED
THE TRIGGER TO STICK IN FIRED POSITION, WHEN THE
ACTION WAS CLOSED THE FIRING PIN FOLLOWED DOWN
FIRED THE ROUND

1 of 1