

1. NO GUN EXAMINATION REPORT NUMBER: \_\_\_\_\_ MODEL: 700 BDL  
 GENERAL CONDITION: NEW R #: 002023  
 OUTSIDE WORK: NO DATE: 1-27-72  
 FIRED AMMO TYPE: \_\_\_\_\_ FROM: BAY CITY HDQ. CO.  
 & CONDITION: \_\_\_\_\_ BAY CITY, MICH.  
 GUN #: 6500965  
 PROOF: R.E.P.-M INSP.: \_\_\_\_\_ TEST: 13 CODE: NONE  
 HEADING: O.K. GA./CAL.: 243 WIN.  
 BREECH OPENING: - CHECKED BY: C. PROSSER  
 RECOIL SHOULDERS: O.K. APPROVED: \_\_\_\_\_  
 CHAMBER: O.K. APPROVED: \_\_\_\_\_  
 TEST: NO APPROVED: \_\_\_\_\_  
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: \_\_\_\_\_

MILINE STOCK, TRIGGER PULL 4 1/2 LBS. - O.K. ENGAGEMENT  
.008 (.020 MIN.) NEW RIVETED HOUSING CONNECTOR  
1.093 M/D = 1.080 TRIGGER 1.076 M/D = 1.076 BURS ON  
CONNECTOR SIDES.

PLAINTIFF'S  
EXHIBIT

3261

COMPLAINT: "FIRES ON SAFE"

INCIDENT: MAY HAVE FOLLOWED DOWN WHEN SAFE WAS  
RELEASED.

COMMENTS: ENGAGEMENT IS SET TOO CLOSE, WITH THE  
BURS ON THE CONNECTOR AND CLOSE ENGAGEMENT,  
IT IS POSSIBLE THAT THE CONNECTOR FAILED TO  
RETRACT WHILE THE SAFETY WAS ON THEN FOLLOW  
DOWN OCCURRED WHEN THE SAFETY WAS RELEASED.

1 of 1