

RD-5542-1 Rev. 2-15-61

P		GUN EXAMINATION REPORT NUMBER:		MODEL: MDC-A-2-	
GENERAL CONDITION: NEW				R#: 24361	
OUTSIDE WORK: NO				DATE: 12-13-71	
FIRED AMMO TYPE: -				FROM: JENSEN BYRD Co.	
& CONDITION: ASSEMBLED GO				SPOKANE, WA 992	
PROOF: R.E.P.-1		INSP.: 55	TEST: 49	GUN #: 6411567	
HEADING: O.K.				CODE: AU = 3/71	
BREACH OPENING: -				ST./CAL.: 3006	
RECOIL SHOULDERS: O.K.				CHECKED BY: G. FREDERIC	
CHAMBER: O.K.				APPROVED: _____	
TEST: NO				APPROVED: _____	
COMPONENT CONDITION: (Damaged, Broken, Old Style)				APPROVED: _____	
<p>- NO DAMAGED BROKEN COMPONENTS. TRIGGER IS FULL LENGTH TRIGGER CONNECTOR ENGAGEMENT AND SING-FIRE POSITION HEAD ENGAGEMENT WITHIN SPECIFICATIONS. TRIGGER GUARD TRIGGER GUARD.</p>					
<p>COMPLAINT: FIRES WHEN BOLT IS CLOSED</p>					
<p>INCIDENT: FOLLOW DOWN</p>					
<p>PLAINTIFF'S EXHIBIT 3265</p>					
<p>COMMENTS: THE CUSTOMER'S MALFUNCTION CANNOT BE DETERMINATED. ED. SOME FOREIGN MATERIAL IS NOTED ON THE TRIGGER CONNECTOR WHICH MAY HAVE CAUSED IT TO STICK IN FIRE POSITION, RESULTING IN A FOLLOW DOWN.</p>					

1 of 1

AL 0029797