

GUN EXAMINATION REPORT NUMBER: 700 MODEL: 700
 GENERAL CONDITION: NEW R #: 24195
 OUTSIDE WORK: SEAR ANGLE ON FIRING PIN DATE: 11-30-71
HEAD MAY HAVE BEEN COLORED IN VENTURE FROM: BOES GUN SHOP
 FIRED AMMO TYPE: SCOTT LANSING, MICH.
 & CONDITION: ASSEMBLER 30 GUN #: 6361958
 PROOF: R.E.P.-E INSP.: 9 TEST: 29 CODE: W.T. = 8/70
 HEADING: O.K. GA./CAL.: 7MM REM. MAG.
 BREECH OPENING: - CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: No APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO DAMAGED, OR BROKEN COMPONENTS. SOME FRICTION
MARKS ON TRIGGER AND INSIDE HOUSING. CONNECTOR-
SEAR ENGAGEMENT .005 MIN. F.O.I.S. TRIGGER PULL:
FOUR POUNDS.

COMPLAINT: "GUN DISCHARGES WHEN BOLT IS BEING OPENED"

INCIDENT: FOLLOW DOWN

PLAINTIFF'S
EXHIBIT

3268

COMMENTS: CUSTOMER'S MALFUNCTION NOT DUPLICATED.

IT IS POSSIBLE THAT A SLIGHT TRIGGER PINN CAUSED
FAILURE TO RETRACT, REDUCING THE CONNECTOR-SEAR
ENGAGEMENT SO THAT A MOVEMENT OF THE BOLT
HANDLE RELEASED THE FIRING PIN TO FIRE THE
ROUND IN THE CHAMBER.

1 of 1