

P NO GUN EXAMINATION REPORT NUMBER: _____MODEL: 700 BDLGENERAL CONDITION: GOODR #: 10002OUTSIDE WORK: TRIGGER PULL WEIGHT AND STOPDATE: 4-28-71SCREWS RE-ADJUSTED, SCOPE MOUNTED.FROM: MAX MERHELSTEIN DIST. CO.

FIRED AMMO TYPE: _____

CARBONDALE, PENNA.

& CONDITION: _____

GUN #: 6333602PROOF: R.E.P. - G INSP. INCOMPLETE TEST: 55CODE: CT-4/70HEADING: MAX.GA./CAL.: 25-06BREACH OPENING: -CHECKED BY: C. PROSSERRECOIL SHOULDERS: EXCESSIVE RADIUS REAR CORNER.

APPROVED: _____

CHAMBER: _____

APPROVED: _____

TEST: NO

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

NO DAMAGED, BROKEN COMPONENTS.PLAINTIFF'S
EXHIBIT

3274

COMPLAINT: "BOLT LOCKS SHUT, GUN HAS FIRED WITH SAFETY ON""FACTORY BULLETS SEAT IN RIFLING."

INCIDENT: _____

COMMENTS: CAN NOT DUPLICATE CUSTOMER'S "FIRED WITH SAFETY ON."SEAR-CONNECTOR ENGAGEMENT, 020 - SPECIFICATIONS MIN. 020.

THERE IS EVIDENCE OF CUSTOMER'S RE-ADJUSTING OF TRIGGER
STOP & PULL WEIGHT SCREWS. DECREASING TRIGGER PULL
WENT BUT REDUCES SEAR-CONNECTOR ENGAGEMENT MAKING
A FOLLOW UP DOWN LIKELY.