

1. NO GUN EXAMINATION REPORT NUMBER: \_\_\_\_\_ MODEL: 700  
 GENERAL CONDITION: GOOD R #: 04 04  
 OUTSIDE WORK: NO DATE: 3-1-71  
 FIRED AMMO TYPE: — FROM: GLOBE #10  
 & CONDITION: \_\_\_\_\_ TUCSON, ARIZONA  
 GUN #: 6319824  
 PROOF: R.E.P.-E INSP.: 58 TEST: NO STAMP CODE: AT-3/70  
 HEADING: O.K. GA./CAL.: 270 WIN.  
 BREACH OPENING: — CHECKED BY: C. R. Rauer  
 RECOIL SHOULDERS: O.K. APPROVED: \_\_\_\_\_  
 CHAMBER: O.K. APPROVED: \_\_\_\_\_  
 TEST: NO APPROVED: \_\_\_\_\_  
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: \_\_\_\_\_

NO COMPONENT DAMAGED OR BROKEN. TRIGGER-CONNECTOR  
SEAR ENGAGEMENT 2.005 (MIN. IS .015)

COMPLAINT: FIRES ON CLOSING BOLT

INCIDENT: FOLLOW DOWN

COMMENTS: THE TRIGGER CONNECTOR-SEAR ENGAGEMENT IS  
NOT ENOUGH FOR PROPER SUPPORT, ALLOWS THE  
FIRING PIN TO FOLLOW DOWN.

PLAINTIFF'S  
EXHIBIT

3280

AL 0029812

1 of 1