

Customer Complaint

MODEL: 700 PCL
 R # : 20000
 DATE: 12-10-00
 FROM: FLYNN, D.
 GUN # : 6884951
 CODE: CTR-460
 CAT/CAL.: 25-07
 CHECKED BY: C. F. R. 10
 APPROVED: _____
 APPROVED: _____
 APPROVED: _____
 APPROVED: _____

GENERAL CONDITION: EXCELLENT
 SLIDE GRA: W/O
 RIFLE AND TYPE: _____
 & CONDITION: _____
 PRICE: \$1000.00 INSP.: _____ TEST: _____
 READING: 0.00
 BREACH OPENING: _____
 RECOIL SHOULDERS: _____
 CHAMBER: 0.00
 TEST: NO
 COMPONENT CONDITION: (Damaged, Broken, Old Style)

COMPLAINT: "BULLET STICKS IN CHAMBER ALSO BOLT IS
 IMMOVABLE FOR SOME REASON."

INCIDENT: _____

PLAINTIFF'S
 EXHIBIT

3286

COMMENTS: THE CUSTOMER PULLED THE BULLET OUT OF THE
 CASE LEAVING IT IN THE THROAT. THIS APPARENTLY
 IS AN AMMUNITION PROBLEM (PER M. WALKER).
 THE BOLT CATCHING IS CAUSED BY PUSHING THE
 SAFETY ON BEFORE LOCKING THE BOLT THUS CATCH-
 ING THE SAFETY PIN IN THE LOCKING CAM.