

*Customer Complaint*P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700GENERAL CONDITION: NEW R #: 27774OUTSIDE WORK: NO DATE: 12-10-70FIRED AMMO TYPE: - FROM: KROGER'S FOOD

& CONDITION: _____ SUPPLY

PROOF: R.E.A.A. INSPECTION: 33 TEST: 13 GUN #: 6367225HEADING: - CODE: DT-9/70BREECH OPENING: - G.K./CAL.: 3006RECOIL SHOULDERS: - CHECKED BY: C. PROSSERCHAMBER: - APPROVED: _____TEST: NO APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

COMPONENTS O.K.COMPLAINT: "HAMMER IN BOLT WILL NOT STAY COCKED."INCIDENT: FOLLOWS DOWN.COMMENTS: SEAR, TRIGGER CONNECTOR, ENGAGEMENTADJUSTED TOO CLOSE (.005) MINIMUM IS .015, THIS
LETS THE SEAR SLID OFF THE CONNECTOR UNDER
PRESSURE & FIRING PIN FOLLOWS DOWN.RE-ADJUSTED ENGAGEMENT.PLAINTIFF'S
EXHIBIT

3294

1 of 1
AL 0029827