

P.I. 100 GUN IDENTIFICATION REPORT NUMBER: 700 801
 MODEL: 700 801
 GENERAL CONDITION: Good R #: 38794
 OUTSIDE WORK: No DATE: 10-21-70
 FROM: TL. R. H. Co.
 FIRED AND TYPE: — ESTIM. 1000 YDS.
 & CONDITION: — GUN #: 38794
 PROOF: R.F.P. DISP.: — TEST: ✓ CODE: 2.2 = 410
 HEADING: S.L. GA./CAL.: 300 MIN. R.L.
 BREACH OPENING: — CHECKED BY: E. PROSE
 RECOIL SHOULDERS: — APPROVED: —
 CHAMBER: O.K. APPROVED: —
 TEST: No APPROVED: —
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: —

COMPLAINT: "GUN FIRED WHEN PICKED UP"

INCIDENT: FOLLOWING DATA

COMMENTS: TRIGGER CONNECTOR - SERA ENGAGEMENT DID
MIN. ENGAGEMENT = .015, MALFUNCTION NOT DUPLICATED.
ENGAGEMENT RE-ADJUSTED.

PLAINTIFF'S
EXHIBIT

3297

10 of 1
AL 0029830