

M/700 Fire Control

NE GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 PDL
 GENERAL CONDITION: GOOD R #: 22760
 OUTSIDE WORK: ACT TRIGGER ADJUSTING DATE: 10-16-79

SCREWS UNSEATED, ADJUSTMENTS CHANGED FROM: GENERAL
 FIRED AMMO TYPE: _____ 12.1 INCH

& CONDITION: _____ GUN #: 123512
 PROOF: R.E.P. INSP.: 9 TEST: _____ CODE: WTS = 5/15
LN = 2/15

READING: _____ GA/CAL.: 222

BREECH OPENING: _____ CHECKED BY: J.F. P. 20047

RECOIL SHOULDERS: _____ APPROVED: _____

CHAMBER: _____ APPROVED: _____

TEST: _____ APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

OLD STYLE SEAR-SAFETY SPRING HEAVY OIL USED
TRIGGER CONNECTOR BROKEN

COMPLAINT: FOLLOWS DOWN

INCIDENT: _____

COMMENTS: FOLLOW DOWN WAS CAUSED BY FIVE BROKEN CONNECTORS

PLAINTIFF'S
 EXHIBIT
 3306

181
 AL 0029841